

# **Technical Journal**

### TITLE:

# Check engine lamp and DTC - ECM P050B00

REF NO: TJ 33235.3.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada		
3 US 7	PARTNER: '510 Volvo Car USA	ISSUE DATE: 2019-06-26	STATUS DATE: 2019-06-26	
FUNC GROUP: 2840	FUNC DESC: Control system, fuel supply	Page	1 of 2	

"Right first time in Time"

### **Attachment**

### **Vehicle Type**

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
235	10	B4204T23					2018-2020		-	201717-201924
235	A2	B4204T27					2018-2020		-	201717-201924
236	10	B4204T23					2018-2020		-	201717-201924
236	A2	B4204T27					2018-2020		-	201717-201924
246	10	B4204T23					2018-2020		-	201717-201924
246	A2	B4204T27					2018-2020		-	201717-201924
246	BR	B1FPHEV					2018-2020		-	201717-201924
256	10	B4204T23					2018-2020		-	201717-201924
256	A2	B4204T27					2018-2020		-	201717-201924

# **CSC** Customer Symptom Codes

Code	Description
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication

# VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

# **Technical Journal 33235.3.0**



### **DTC** Diagnostic Trouble Codes

<b>Control Module</b>	Code	Fault Type
ECM	P050B00	Intermittent

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

#### **Text**

### **DESCRIPTION:**

If the check engine lamp may appear after a start in the DIM (Driver Information Module) and the car is running without any drivability issues, follow "service".

### **SERVICE:**

\* A new engine management software is available from 2019w24.

Perform an upgrade of the software according to TJ 31543.

### \*Warranty claim info:

\*To get warranty claim accepted for a job described in this TJ, please use following data: VST OP number 36004-2: Software control module downloading

### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support Not Needed", use function group 2840.

Page 2 of 2 2019-06-26