

## Latest Vehicle Concern Fixes



### Pop Noise from Audio Output

#### Customer Voice:

- Popping sound or crackling noise from the audio system while in use.

#### Technical Description:

- Under investigation, could be IMC or AAM software

#### Status:

- Primarily reported on Range Rover Velar or Land Rover Discovery
- Please raise a TA if a customer exhibits this concern and is not being caused by a hardware failure of the speaker system

17MY – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport with InControl Touch Pro Audio System

