

ServiceNews Article

July 2019

B19070D Version 1

Radio Stays On with Ignition OFF

AFFECTED VEHICLES

Year	Model	Trim
2019	RDX	ALL

Are you having this issue while using Apple CarPlay?

- CarPlay beeps and stops working.
- If you try to switch to a different audio source, you see the message XM-Check Tuner or FM-Radio Unavailable.
- When you turn the ignition to OFF, the navigation display stays on.

We're aware of this issue and have it under investigation. So far, we know it's software related, so don't replace any components. When we come up with a fix, we'll release an OTA software update.

As a temporary measure, just remove and install the radio backup fuse or disconnect and connect the battery. This will reset the system.