



# Technical Journal

TITLE:

**High oil consumption.  
Engine 61**REF NO:  
**TJ 34588.2.0**ISSUING DEPARTMENT:  
**Technical Service**CAR MARKET:  
**United States and Canada**PARTNER:  
**3 US 7510 Volvo Car USA**ISSUE DATE:  
**2019-04-16**STATUS DATE:  
**2019-06-20**FUNC GROUP:  
**2100**FUNC DESC:  
**Engine**

Page 1 of 13

**“Right first time in Time”**

## Attachment

File Name	File Size
TJI-481117-2_1_1_en-US.pdf	2.2471 MB

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
124	61	B5254T12					2013-2014		-	201220-201345
134	61	B5254T12					2013-2016		-	201220-201616
136	61	B5254T12					2016-2016		-	201517-201619
137	61	B5254T12					2016-2016		-	201524-201616
138	61	B5254T12					2016-2016		-	201521-201616
155	61	B5254T12					2014-2016		-	201349-201616
156	61	B5254T12					2015-2016		-	201420-201616

## CSC Customer Symptom Codes

Code	Description
AZ	Lubrication and oil system/Excessive oil consumption

## VST Operation Number

VST Operation Number	Description
98575-2	Piston ring replacement



## **DTC** Diagnostic Trouble Codes

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

## **Text**

### **DESCRIPTION:**

\* Vehicle type and TJI changed.

If customer experience “Low oil pressure light” coming on. No external leakage.

High engine oil consumption may occur. Follow the instructions under “Service”

### **SERVICE:**

Replace piston ring kit according to attached instruction.

### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area “Vehicle Report” and sub concern area “Support not needed”, use function group 2100.

**To view TJ attachment continue to next page. This TJ has one attachments.**