

# Technical Service Bulletin

Mazda North American Operations  
Irvine, CA 92618-2922



<b>Subject:</b>  <b>MAZDA CONNECT UNEXPECTEDLY ANNOUNCES SPEED LIMIT WHEN CMU WAKES UP</b>	<b>Bulletin No.:</b> 09-028/19
	<b>Last Issued:</b> 07/15/2019

## APPLICABLE MODEL(S)/VINS

2019 Mazda3 (with Navigation)

## DESCRIPTION

Some customers may experience that the MAZDA CONNECT unexpectedly announces the speed limit when the Connectivity Master Unit (CMU) wakes up, regardless of the ignition switch position (ON / ACC / OFF). The speed limit is announced when the vehicle is unlocked and a door is opened (waking up the CMU) without touching the start button.

This concern occurs on the vehicles located in Canada and Mexico including those driven to and from the U.S. It is caused by improper CMU software and the unnecessary speed limit announcement function left activated at the factory. To correct the concern, the CMU software has been modified and the speed limit announcement function has been removed.

## REPAIR PROCEDURE

1. Verify customer concern.
2. Update the CMU to the software version 7000C0A-NA01\_10018 or later using the MAZDA CONNECT Update Instructions on MGSS.

**NOTE:** Advise the customer that if they noticed the speed limit announcement when they passed the country border, this function is not intended to be active and has been removed with the repair.

3. Verify the repair.

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

## WARRANTY INFORMATION

### NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	64
Damage Code	9W
Part Number Main Cause	5555-RP-CMU
Quantity	0
Operation Number / Labor Hours:	XXR83XFX / 0.2 Hrs.

Period Covered: Normal Warranty Period

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.