

Technical Service Bulletin

43 Multiple warnings messages and/or lights in the cluster, DTC B200FF5 and/or B200FF3 stored in the suspension module

43 19 30 2055705/1 July 26, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
Audi e-tron quattro	2019 – 2020	All	Not Applicable	

Condition

Customer states:

Multiple warning messages in the cluster.

And/or

• Multiple warning lights in the cluster.

Workshop findings:

One or more of the following DTCs may be stored in the suspension control module, J775 (address word 0074):

- DTC B200FF5 (Internal malfunction).
- DTC B200FF3 (Internal malfunction).

Technical Background

The DTCs are caused by a timing issue within the memory access of the suspension control module.

Production Solution

Improved software is being prepared.

Service

Clear the DTCs and release the vehicle.



If there are additional DTCs in the suspension control module, please follow the test plan to resolve the issue.



Technical Service Bulletin

Warranty

Claim Type:	 110 up to 48 Months/50,000 Miles. G10 for CPO Covered Vehicles – Verify Owner. If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. 			
Service Number:	4316			
Damage Code:	0040			
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)	
	Road test prior to the service procedure	No allowance	0 TU	
	Road test after the service procedure	No allowance	0 TU	
Claim Comment:	As per TSB #2055705/1			

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2055705) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.