


Latest Vehicle Concern Fixes



NLI – Bluetooth connectivity concerns with Android equipped device	14 – 19MY F-PACE, F-TYPE, XE, XF, XJ, RR Evoque, Discovery, Discovery Sport with InControl Touch NLI Infotainment System
<p>Customer Voice:</p> <ul style="list-style-type: none">Intermittent Bluetooth connection on Android equipped device with software 9.0 <p>Technical Description:</p> <ul style="list-style-type: none">Under investigation with suppliers (Infotainment system & cellphone suppliers) <p>Status:</p> <ul style="list-style-type: none">LR – SSM 74446 has been released on June 7th 2019JAG – SSM 74447 has been released on June 7th 2019NLI software is expected to be released by July 31st 2019.	 <p>The image shows three smartphone screens. The leftmost screen is a lock screen with a purple geometric pattern, displaying the time 12:45 and the date FRI, MARCH 11. The middle screen is a home screen with a large white letter 'B' on a light background, displaying the date Tuesday, Oct 9 and the temperature 68°F. The rightmost screen is a 'Software information' page with the following details:</p> <ul style="list-style-type: none">One UI version: 9.0Android version: 9Baseband version: C960NV1.33253.00Kernel version: 4.9.110-131 (g92; #3 Tue Jan 29 17:14:13 KST 2019)Build number: PPST1.180019.011.C960NV1.33253.00SE for Android status: Following: SEP9_03M_C960NV_9_0001 Tue Jan 29 18:47:26 2019Knox version: Knox 2.21; Knox 4.0; SecureWorld 2.7; TAMA 4.0.0Service provider SW ver.

