

Subject: Engineering Information – Burning Smell, Potential Loss of Driveability, No Start/Crank and/or Unwanted Windshield Wiper Activation

This EI has been revised to end the need for information from the field. Please discard PIE0508A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu	2016	2019				

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	3
Modified	Released February 13, 2019 May 16, 2019 – Updated the Subject and Condition. July 12, 2019 – Ended the need for further information from the field.