

Subject: Engineering Information – Instrument Panel Upper Skin Delaminating Near Passenger Airbag Door

This PI has been revised to end the need for information from the field. Please discard PIE0510.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	XT5	2017	2019				

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released February 19, 2019 Revised July 09, 2019 – Ended the need for further information from the field.