

Subject: Engineering Information – Hard Start and/or No Start, DTCs P0087, P0088, P0191, P128E Set and/or Fuel Injector Pump Replacement

This PI has been revised to end the need for information from the field. Please discard PIE0523A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado	2015	2016			Equipped with 6.6L Engine (RPO LML)	
GMC	Sierra						

If you encounter a vehicle with the above condition, refer to bulletin 16-NA-102 for further diagnosis.

Version	3
Modified	Released May 17, 2019 Revised May 22, 2019 – Revised to update the Engine RPO. Revised July 24, 2019 – Ended the need for further information from the field.