

Subject: Engineering Information – Noise Heard From Rear Shock Absorber

This PI has been revised to end the need for information from the field. Please discard PIE0524.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2018	2019			Equipped with 3.6L Engine (RPO LFY)	Equipped with Automatic Transmission (RPO M3W)
Chevrolet	Traverse						Equipped with Automatic Transmission (RPO M3V)

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released May 21, 2019 Revised July 24, 2019 – Ended the need for further information from the field.