

August 13, 2019

Version 2

Product Update: 2019 Civic Si Summer Tire Label Mismatch

This bulletin is canceled as the campaign has expired.

This product update has expired. If you did the repair indicated in this bulletin on or before August 1, 2019, use the warranty information to file a claim.

WARRANTY CLAIM INFORMATION

Repair Procedure A - Customer Acknowledgement

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
4350A4	Customer acknowledgement. Update the VIN status.	0.2 hr	6TR00	A3R00	A19007A	42751-GYR-055

Skill Level: Service Advisor

Repair Procedure B - Replace Tires and Placard, Change VSA Threshold, and Calibrate TPMS

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
4211H8	Mount and balance four all-season tires. Replace the tire placard on the driver's door jamb. Change VSA threshold and calibrate TPMS.	1.4 hr	6TR00	A3R00	A19007B	42751-GYR-055

Skill Level: Repair Technician

Repair Procedure C - Replace Monroney Label

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8290A3	Replace the Monroney label. Can be done on the service drive.	0.2 hr	6TR00	A3R00	A19007C	42751-GYR-055

Skill Level: Service Advisor/Porter/Sales Staff

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

END