

**August 16, 2019**

Version 2

**Rattle/Squeak from the Head Up Display (HUD) Area**Supersede 19-083, dated July 17, 2019, to revise the information highlighted in **yellow**.**AFFECTED VEHICLES**

Year	Model	Trim	VIN Range
2018-19	Accord	Touring	ALL
2018-19	Accord Hybrid	ALL	ALL

**REVISION SUMMARY**

This bulletin has been temporarily suspended; it will be revised and reposted in the future. If you did the repair indicated in this bulletin prior to August 17, 2019, make sure to use the warranty claim information provided below

**WARRANTY CLAIM INFORMATION**

The normal warranty applies.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
7381C7	Remove the dashboard, to access the HUD.	2.6 hr	07406	04201	A19083A	78200-TVA-A01
A	Apply wool felt to the HUD trim and plastic lens.	0.3 hr				

Skill Level: Repair Technician

END

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.