

# Special Service Message

NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

## SSM 74501 - Range Rover / Range Rover Sport - Roof Blind Foam Strip Becomes Loose or Adrift

**Models :** Range Rover / L405 (SALGA2KEXDA000001 - SALGS2SV9KA567472)

Range Rover Sport / L494 (SALWA2PF1EA000001 - SALWR2RU9KA875892)

**Engineer** Chris Davies

**Name :**

**Last** 30 JUL 2019 15:22:49

**Modified :**

**Category :** Body

**Symptom :** 105000 Roof Options

**Content :** Issue:

Roof Blind Foam Strip becomes loose or adrift, this may cause the blind to bind / jam

Cause:

Roof blind foam strip has come adrift due to the adhesion fails due inconsistent fitment process during vehicle production

Action:

If you see a Foam Strip coming adrift (see images attached 1.0 & 2.0), remove the Foam Strip, clean the adhesive area and **do not replace it**

**File :** [2.0 Customer Symptom - Foam Strip Loose Adrift when Roof Blind Open.JPG](#)  
[1.0 Customer Symptom - Foam Strip Loose on the Roof Blind.JPG](#)