

## Latest Vehicle Concern Fixes



AJ20P6 eSC DTC P00B0-49	2019 RR Sport with AJ20P6
<p><b><u>Customer Voice:</u></b></p> <ul style="list-style-type: none"><li>• The Check Engine Lamp is illuminated.</li></ul> <p><b><u>Technical Description:</u></b></p> <ul style="list-style-type: none"><li>• DTC P00B0-49 or 45129-49 is stored in the PCM.</li><li>• Internal failure of the electronic supercharger.</li></ul> <p><b><u>Status:</u></b></p> <ul style="list-style-type: none"><li>• Should diagnosis lead to replacement of the eSC, obtain a picture of the serial number and WERS number of the original part.</li><li>• Create an EPQR and include the aforementioned picture along with contact information for someone at the retailer who can serve as the point of contact for the shipping company to collect the part.</li></ul>	

