

Latest Vehicle Concern Fixes



Coolant Leaks in AJ20P6 equipped vehicles

2019 RR Sport with AJ20P6

Customer Voice:

- There is a fluid leak from the vehicle.

Technical Description:

- A leak is identified from the engine cooling system.

Status:

- There have been reports of leaks from multiple locations in the engine cooling system at PDI or low TIS.
- It is essential that an EPQR is raised including clear pictures and/or videos of the leak and an image from TOPIx or EPC, if necessary, to identify location.
- Also include contact information for someone in the retailer who can support PRR in the EPQR.

