Latest Vehicle Concern Fixes





No Audio Output or Loss of Audio	19 – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport with InControl Touch Pro Audio System
 Customer Voice: Customer states there is no audio output from the speakers on all sources 	
Technical Description: • IMC hardware failure	
 Status: Primarily reported on 19MY vehicles Currently investigating parts stock Please submit an EPQR if you come across this scenario. 	