Latest Vehicle Concern Fixes



Broken / Cracked TPMS Valve Stems	17MY- Onwards RR Velar, Range Rover, RR Sport, RR Evoque, Discovery, Discovery Sport, E-PACE, F-PACE, I-PACE, F-TYPE, XJ, XE, and XF
 Customer Voice: The tire valve stem is broken or cracked. Technical Description: This damage may be caused by the use of an extended tire inflation chuck. Status: Damage due to the use of the extended tire inflation chuck should not be claimed under warranty. Warranty will be calling back TPMS sensors and valve stems for inspection. 	Image: Window Structure Image: Structure