


Latest Vehicle Concern Fixes



| Air Conditioning Not Cooling | Discovery 19MY |
|---|--|
| <p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Customers may report that the air conditioning system is not blowing cold air from the HVAC vents. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• This may be caused by a refrigerant line that has been kinked during manufacturing, restricting the flow of refrigerant around the system. <p><u>Status:</u></p> <ul style="list-style-type: none">• The process for installing the refrigerant line has been corrected in manufacturing with a containment VIN of K2413394.• A SSM is due to be published for this concern, providing repair guidance. |  |

