

Latest Vehicle Concern Fixes



Hood Release Lever May Become Detached

New Range Rover Evoque 20MY

Customer Voice:

- A customer may express a concern that the hood release lever has become detached during operation.

Technical Description:

- This may be caused by insufficient fastening of the hood release lever.

Status:

- A revised lever assembly has been developed to address this concern.
- TSB LTB01303NAS1 will be published once sufficient part stock is on hand of the revised lever assembly.
- Should a customer express a concern, please refer to the TSB for repair guidance.

