

Latest Vehicle Concern Fixes



Outer Tail Lamp Water Ingress/ Lenses Cracking

New Range Rover Evoque 20MY

Customer Voice:

- A customer may express a concern of moisture in the outer tail lamp or cracking of the outer tail lamp lenses and or a squeak type noise from the rear of the vehicle while driving.

Technical Description:

- This may be caused by an insufficient gap between the outer tail lamp and the rear quarter panel.

Status:

- TSB LTB01304NAS1 is being published to provide outer tail lamp to body clearance checks and adjustment procedures.
- Should a customer express a concern, please refer to the TSB for repair guidance.

