Service Information Bulletin

Engine

DELIVERY STOP: CAMSHAFT SENSORS

MODEL

Engineering Designation	Model Description	Production Date
F90	M5 Sedan	7/1/2019 - 7/2/2019
F91	M8 Convertible	7/3/2019 – 7/4/2019
G12	7 Series Sedan	7/1/2019 – 7/3/2019
G16	8 Series Gran Coupe	7/1/2019 – 7/16/2019
G30	5 Series Sedan	7/2/2019 - 7/19/2019

AFFECTED VEHICLES

Vehicles which require this Delivery Stop to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), with the Key Reader or Warranty Vehicle Inquiry. All other systems will show the stop sale starting tomorrow.

SITUATION

BMW of North America, LLC has issued a Delivery Stop (effective July 31, 2019) on a small number of Model Year 2020 BMW vehicles that were produced between July 1, 2019 and July 19, 2019.

Approximately 65 vehicles are affected by this delivery stop.

On affected vehicles, the camshaft sensors will be inspected and, if necessary, replaced.

The bulletin will be updated when additional information becomes available.