

## **Service Bulletin**

## INFORMATION

## Subject: Information on Elimination of Glove Box Dampener, When Unlatched Glove Box Door Falls Open

Brand:	Model:	Model Year:		Date Breakpoint:		Engine:	Transmission:
Branu.	woder.	from	to	from	to		
Chevrolet	Colorado	2019	2019	SOP	Prior to May	All	All
GMC	Canyon	2019	2019	30F	7, 2019	All	All

Involved Region or Country	North America, N.A. Export Regions				
Additional Options (RPOs)	EXC - LUXURY EDITION, DENALI (Y91)				
Condition	Some customers may comment that when unlatching their glove box, the door falls open quicker than they've seen on other same models.				
Cause	The cause of the condition is that the Denali models contain a glove box dampener (2). The cause of the condition is that the Denali models contain a glove box dampener (2).				
Correction	Note: This is NOT a warranty issue and this damper should NOT be installed to vehicles not equipped with it.				
Correction	Please communicate to the customer that the glove box is functioning as designed and this is a normal condition of their vehicle. Please share this information with the customer, including a copy of this message				

Version	1
Modified	Released July 16, 2019

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION