



Service Bulletin

Bulletin No.: 19-NA-161

Date: July, 2019

TECHNICAL

Subject: Trailer Hitch Cover Loose

Brand:	Model:	Model Year:		Date Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer	2019	2019	All	All	All	All

Involved Region or Country	North America, N.A. Export Regions
Additional Options	Blazer Model
Condition	Some customers may comment that the hitch cover is coming loose from the rear fascia.
Cause	The cause of the condition may be that the attachment holes on the mating rear fascia skid plate are enlarged.
Correction	<div style="text-align: center;"> </div> <p style="text-align: right; font-size: small;">5375272</p> <p>Replace the rear bumper fascia lower skid plate (4). Refer to <i>Rear Bumper Fascia Lower Skid Plate Replacement</i>, in SI.</p>

Parts Information

Causal Part	Description	Part Number	Qty
X	PLATE PKG-RR BPR FASCIA LWR SKID	84557395	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
1421440	Rear Bumper Fascia Lower Skid Plate Replacement	1.8 hr.*
*The September 1 update of the Labor Time Guide will contain this change.		

Version	1
Modified	Released July 17, 2019

