

# WORK DESCRIPTION FOR FIELD MEASURE

Code: 19P5498301

Version: 2.0

## Update control unit software for AMG Drive Unit, active engine mounts, and electric differential lock

Model 205

- i** • Ensure use of **XENTRY Diagnosis version BD/DVD (03/2019)** or higher.
- Before starting the work procedure, install all the **add-ons that are updated daily** in **XENTRY Diagnosis**.
- Please make sure to follow the operation steps exactly as described in XENTRY Diagnosis.
- Use a battery charger to ensure sufficient power supply of the vehicle **on-board electrical system battery** (greater than 12.5 V).
- If XENTRY Diagnosis is already connected to the vehicle, start with **operation step 2**.
  - i** If two or more software updates or SCN codings are performed during one workshop visit, operation items 02-4762 and 02-5058 may be invoiced **only once for each workshop order!**

### Work procedure

1. Connect XENTRY Diagnosis.
2. Update control unit software for **AMG Drive Unit (DRVU\_NG), active engine mounts (AMLA), electric differential lock (EAGGS)**.
  - i** To do this, select menu item "Quick test view – **N145/1 AMG Drive Unit** – Adaptations – Control unit update – Update of control unit software".
  - i** Then follow the user guidance in XENTRY Diagnosis.
  - i** Additional control units will be updated **automatically** in the background if necessary.
3. Disconnect XENTRY Diagnosis.

### Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-9334*	Update control unit software for <b>AMG Drive Unit (DRVU_NG), active engine mounts (AMLA), electric differential lock (EAGGS)</b> (XENTRY Diagnosis connected)	0.1 h	54 983 01
02-4762*	Connect/disconnect vehicle diagnosis system (XENTRY Diagnosis)	0.1 h	54 983 01
02-5058*	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)	0.1 h	54 983 01

\* Operation item may be invoiced only once for each workshop order!

Mercedes-Benz  
Global Service & Parts