

WORK DESCRIPTION FOR FIELD MEASURE

Code: 19P9790001

Version: 2.0

Rework left A-pillar

Model 238

Work procedure

1. Remove left front door.
i For basic data, see AR72.10-P-0500LWO.
2. Lift cover (1) between fender and A-pillar.
3. Subsequently seal transition between A-pillar cover plate and roof frame (Figure 1) with seam seal.
i The sealing may not have been applied correctly.




Figure 1

4. Assemble in reverse order.

Parts

Quantity	Designation	Part no.
1	Transparent seam seal	A 000 989 32 00

- i** Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealants, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-3697	Rework left A-pillar	0.6 h	97 900 01

Mercedes-Benz
Global Service & Parts