



Technical Service Bulletin

91 MIB2+: DTC B200087 is stored in the information electronics control module

91 19 83 2055966/1 August 28, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, A8, Q8, and Audi e-tron quattro	2019	All	With MIB2+

Condition

Customer states:

- No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

The following DTC may be stored in the information electronics control module 1, J794 (address word 005F):

- **DTC B200087** (control unit software incompatible, static).

Technical Background

The DTC is logged because of an unintentional data lookup in the information electronics control module 1, J794 (address word 005F) which does not lead to any result. The DTC cannot be deleted, however, there is no restricted functionality.

Production Solution

Not applicable.

Service

A pdf document containing two files (autorun and autorun.sig) is attached to this TSB. These files must be copied from the pdf document to an SD Card as specified below to form the repair script.

1. Copy the two files on a freshly formatted SD card (max. 32GB, formatted to FAT32).
2. Wait for the MMI system to be fully booted (approx. 2 minutes).
3. Insert the SD card in the SD slot. After a short time a green screen should appear.
4. Afterwards, restart the MMI by holding the volume control button (approx. 30 seconds).
5. Clear the DTC in ODIS.



Technical Service Bulletin

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9196		
Damage Code:	0039		
Labor Operations:	Program display and operating unit	9196 2599	20 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2055966/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Tool Number	Tool Description
Shop Tool	SD Card

Additional Information

All parts and service references provided in this TSB (2055966) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.