

SSM 48128 - 2019 Transit Connect - AC Outlet Inoperative

Some 2019 Transit Connect vehicles may exhibit an inoperative AC outlet. This may be due to an inoperative DC/AC inverter. Do not attempt any repairs at this time. Engineering is investigating, monitor OASIS for updates.