



SERVICE BULLETIN

Classification: BT14-016a	Reference: NTB14-063a	Date: August 1, 2019
-------------------------------------	---------------------------------	--------------------------------

370Z ROADSTER; STORAGE LID RUBS THE FIFTH BOW WHEN OPENING THE SOFT TOP

APPLIED VEHICLE: 2010-2014 370Z Roadster (Z34)

This bulletin has been superseded to NTB19-061. Please discard previous versions of this bulletin.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
July 8, 2014	NTB14-063	Original bulletin published
August 1, 2019	NTB14-063a	Amended to supersede

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.