



# Preliminary Information

## PIC6371 Installation Of GM Accessory LPO Wheels 56H, 56M, 57S, or 56K

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Camaro	2020	All	All	All	All

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Involved Region or Country	North America
Additional LPO's	GM Accessory wheel LPO's 56H, 56M, 57S, or 56K
Condition	Some dealers may have questions regarding the installation of the GM Accessory wheels for this vehicle. These wheels will <u>not</u> arrive from the ADI with tire pressure monitor sensors installed.
Concern	The Accessory LPO wheel-only packages for the 2020 Camaro SS do not include the Tire Pressure Monitor sensors.

**Correction:**

Dealers are to first remove the TPM sensors from the stock wheels and then they are to install them into the GM Accessory wheels. The use of TPM service kits is required.

Parts Information

Part Number	Description	QTY
13507403	TPM service kit (includes nut, cap, valve, and washers)	4

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
0590032	PDI - Dealer Installed - Factory Invoiced Options	Use published labor time for LPO.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

Version History

Version	1
Modified	08/07/2019 Created on

