



Preliminary Information

PIT5702 Installation of Upfitter Auxiliary Switches (RPO 9L7)

Models

| Brand: | Model: | Model Years: | VIN: | | Engine: | Transmissions: |
|-----------|----------------------------|--------------|------|-----|---------|----------------|
| | | | from | to | | |
| Chevrolet | Silverado 1500 (New Model) | 2019 | All | All | All | All |
| Chevrolet | Silverado 2500HD/3500HD | 2020 | All | All | All | All |
| GMC | Sierra 1500 (New Model) | 2019 | All | All | All | All |
| GMC | Sierra 2500HD/3500HD | 2020 | All | All | All | All |

| | |
|----------------------------|---|
| Involved Region or Country | North America |
| Additional Options (RPO) | 9L7 |
| Condition | A Dealer or Upfitter may be looking for information on installing RPO 9L7 Upfitter Auxiliary Switches. The Upfitter Auxiliary Switches are located under the climate controls in the center of the dash. |
| Cause | Information not readily available in Service Information (SI.) |

Correction:

Reference the latest version of GM Upfitter Integration Bulletin 153. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

Version History

| | |
|----------|-------------------------|
| Version | 1 |
| Modified | 08/07/2019 - Created on |



GENERAL MOTORS