



Preliminary Information

PIC5141B B1446 Or B1447 On 09 Saturn Vue Hybrid After Module Replacement

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Saturn	Vue Hybrid	2009	All	All	All	All

Supersession Statement

This PI has been superseded to edit the handling process. Please disregard PIC5141A.

Condition / Concern

A B1446 or B1447 may appear after module replacement or after performing the Canada upgrade outlined in the latest version of bulletin [15-08-44-001](#) on a 2009 Saturn Vue Hybrid due to a software anomaly in the setup procedure.

The 2009 Saturn Vue Hybrid is not equipped with an OnStar backup battery.

Recommendations / Instructions

Please record the new module P/N, STID, MEID, MIN, MDN and call GM Technical Assistance for further assistance.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
0602058	Onstar programming	.3 hrs

