



Bulletin No.: PIT5704  
Published date: 08/16/2019

# Preliminary Information

## PIT5704 Seat Back Lift Assist Spring Detached


Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	XT6	2020	All	All	All	All
Chevrolet	Blazer	2019	All	All	All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	A customer or dealer may find a spring lying on the passenger side floor or it may be noticed that a spring has become detached from the rear 60% seat.
<b>Cause</b>	Poor retention of the rear seat back lift assist spring to the seat structure.

**Correction:**

Reinstall the outboard spring on the 60 percent seat in the area shown below.



Reinstall the spring as demonstrated in the video.

**Please view this PI in SI (Service Information) to see the video.**

## Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
7086328	Re-install outboard seat back lift spring on 60% seat	.2
*This is a unique Labor Operation for Bulletin use only.		

## Version History

Version	1
Modified	08/16/2019 - Created on



© 2019 General Motors. All Rights Reserved.