

Bulletin No.: PIT5696A Published date: 08/22/2019

Preliminary Information

PIT5696A ABS / TCS MIL On Code C0010.5A Stored

<u>Models</u>

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions:
			from	to	Engine:	Transmissions.
Buick	Envision	2018 - 2019	All	All	All	All
Chevrolet	Colorado	2018 - 2019	All	All	All	All
Chevrolet	Equinox	2018 - 2019	All	All	All	All
GMC	Canyon	2018 - 2019	All	All	All	All
GMC	Terrain	2018 - 2019	All	All	All	All

Involved Region or Country:	North America
Condition:	ABS / TCS MIL on, Code C0010.5A stored in EBCM. Possible OnStar notification.
	Engineering is looking into the cause of this code . There currently have been no cases of a functional concern regarding this code so if the C0010.5A is stored alone, clear the code and road test. If the C0010.5A is stored with other communication or component codes diagnose those codes.

Correction:

If the code C0010.5A is the only code stored clear the code and road test, engineering is investigating the cause.

Version History

Version	2
Modified	06/28/2019 - Created on
Modified	08/22/2019- Updated Title



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.