



Bulletin No.: PIT5705
Published date: 08/30/2019

Preliminary Information

PIT5705 Creak/Pop Noise From Front Over Bumps

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2015 - 2020	All	All	All	All
GMC	Canyon	2015 - 2020	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment on a pop and/or creak noise from the drivers side front over bumps.
Cause	Inspect for source of noise at the battery hold down retainer on top of the battery where it contacts the inner fender.

Correction:

Remove Battery Hold Down Retainer and inspect for contact marks. Insulate with tape or foam and reinstall.

Version History

Version	1
Modified	8/30/2019 - Created



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.