

## 453 smart audio system - DTC B134155 can be ignored

---

|                   |                                                           |
|-------------------|-----------------------------------------------------------|
| Topic number      | LI82.60-P-070061                                          |
| Version           | 1                                                         |
| Function group    | 82.60 Radio, audio, video systems                         |
| Date              | 08-01-2019                                                |
| Validity          | smart 453 with audio system SA code 537, 561, 505, or 562 |
| Reason for change |                                                           |
| Reason for block  |                                                           |

---

### Complaint:

During a quick test, fault code B134155 'The control unit has a malfunction. The component is not configured' may be displayed and cannot be cleared.

Note: This DTC can be ignored as it does not affect system functionality.

### Cause:

Current smart audio system software

### Remedy:

Do not replace any parts. This LI will be updated with any further developments.

| Symptoms                                                             |
|----------------------------------------------------------------------|
| Overall vehicle / Networking / Diagnosis/software / Current problems |

| Control unit/fault code                             |            |            |
|-----------------------------------------------------|------------|------------|
| Control unit                                        | Fault code | Fault text |
| A2 - Radio - Smart Audio System (Audio) (R0_13_453) | -          | -          |