

Vehicle is temporarily unable to be locked or unlocked using Keyless-Go

Topic number	LI80.61-P-069914
Version	2
Function group	80.61 Keyless-Go/Keyless-Entry
Date	08-26-2019
Validity	Model series 167 with code 889 as of SOP
Reason for change	Cause established
Reason for block	

Complaint:

The vehicle is temporarily unable to be locked or unlocked using Keyless-Go, but can be unlocked/locked via the key fob.

Cause:

The LF (low frequency) parameters may not be optimal.

Remedy:

Repeating SCN coding of electronic ignition lock.

Symptoms
Overall vehicle / Safety and locking system / Keyless go / Function / Vehicle does not open
Overall vehicle / Safety and locking system / Keyless go / Function / Vehicle does not close using door handle