CLEXUS	Tech Tip	L-TT-0266-19	August 08, 2019
Front Stabilizer Nut L	Loose		Market USA
Service Category Suspension		section Front Suspension	
Applicability 2019 ES350 (F-Sport)			
APPLICABLE VEHICLES			
2019		ES350	
CONDITION			
Some customers may experience abnormal noise from the front suspension on 2019 ES350 F-Sport models. Noise frequently comes from the left-front of the vehicle while going over bumps.			
RECOMMENDATIONS			
Confirm torque condition of the Stabilizer Bar (LH & RH). 48811 48553F 48553F 48820A	e Front Stabilize	er Nut - connecting the From	t Stabilizer Link to the Front
If nut is loose, visually inspect the Front Stabilizer Nut, Link and Bar for damage.			
If damage is visible, replace the affected component(s) per Repair Manual. If no damage is visible, tighten Front Stabilizer Nut to torque specification in Repair Manual.			
LINK REFERENCES			
1. <u>FRONT SUSPENSION</u> ES350 [06/2018 - ????		BILIZER BAR: COMPONEN	TS; 2019 - 2020 MY ES300H
Expires on 02/08/2020	© 2019, Lexus, ;	a Division of Toyota Motor Sales, U	SA Page 1 of 1

Ver. 3.0 01/01/2019 L

© 2019, Lexus, a Division of Toyota Motor Sales, USA

Page 1 of 1