

Subject		Market
Intermediate Shaft Tightness		USA
Service Category	Section	
Steering	Steering Gear/Linkage	
Applicability		
2018-2019 Camry and Camry HV		

APPLICABLE VEHICLES


2018-2019	Camry	2018-2019	Camry HV
-----------	-------	-----------	----------

CONDITION

Some customers may experience “tightness” when turning the steering wheel. No Power Steering DTCs are recorded.

RECOMMENDATIONS

- Confirm that condition is isolated to the lower U-Joint of the Steering Intermediate Shaft.



- Follow Repair Manual instructions to replace the vehicle's Steering Intermediate Shaft Assembly.

LINK REFERENCES

This Tech Tip does not contain any link references