


Latest Vehicle Concern Fixes



Check Engine Light with P0521 - 84/85 Stored in the PCM	17MY F-PACE Equipped with AJ20-D4
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Customer may experience a Check Engine Light on the Instrument Cluster <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• P0521-84/85 is stored in the PCM for <p><u>Status:</u></p> <ul style="list-style-type: none">• SSM 74504 is currently posted in GCM & TOPIx• Follow TOPIx for guidance• If no other root cause is found, verify the production date. Only if the vehicle has a production date between 19-September-2016 and 26-September-2016, replace the oil pump. If the vehicle is outside of the aforementioned production dates, raise a TA.• All replaced parts will be called back for warranty analysis.	 A 3D CAD model of a complex engine component, likely a valve train or timing mechanism, shown in a light gray color. It features various ports, bolts, and a central circular opening.

