

Latest Vehicle Concern Fixes



<h2>Pop Noise from Audio Output</h2>	<p>17 – 20MY E-PACE, F-PACE, I-PACE, J-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport with InControl Touch Pro Audio System</p>
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Popping sound or crackling noise from the audio system while in use. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• Under investigation, could be IMC or AAM software <p><u>Status:</u></p> <ul style="list-style-type: none">• Primarily reported on Range Rover Velar or Land Rover Discovery• Please submit a TA case with primary and secondary diagnosis with video recording of the information below:<ul style="list-style-type: none">• 1 kHz sine wave test from a usb stick• 1 kHz sine wave test from a Bluetooth audio source• Play classical music or talk show radio from FM / AM source• Play classical music or talk show radio from Satellite radio source• Issue resolution to be implemented by 19B to be released in September.	

