

Service Bulletin

Bulletin No.: 19-NA-159

Date: August, 2019

INFORMATION

Subject: Information on Elimination of Glove Box Dampener, When Unlatched Glove Box Door Falls Open

Brand:	Model:	Model Year:		Date Breakpoint:		Engine:	Transmission:
Brand.		from	to	from	to		
Chevrolet	Colorado	2019	2020	May 7, 2019	EOP	All	All
GMC	Canyon	2019	2020	iviay 1, 2019	EUP	All	All

Involved Region or Country	North America, N.A. Export Regions				
Additional Options (RPOs)	EXC - LUXURY EDITION, DENALI (Y91)				
Condition	Some customers may comment that when unlatching their glove box, the door falls open quicker than they've seen on other same models.				
Cause	The cause of the condition is that the Denali models contain a glove box dampener (2) which allows the door to lower at a slower, controlled pace, but this dampener was intentionally removed from all other models. This is NOT a mis-build condition and no repairs are necessary.				
Correction	Note: This is NOT a warranty issue and this damper should NOT be installed to vehicles not equipped with it.				
Correction	Please communicate to the customer that the glove box is functioning as designed and this is a normal condition of their vehicle. Please share this information with the customer, including a copy of this message				

Version	2	
Modified	Released July 16, 2019	
	Revised August 19, 2019 – Added 2020 Model year and Corrected Breakpoint	