



Service Bulletin

Bulletin No.: 19-NA-185

Date: August, 2019

INFORMATION

Subject: Steering Wheel Shimmy/Shaking

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu	2016	2020			All	All

Involved Region or Country	North America, N.A. Export Regions
Condition	Some customers may comment that if they release their hands from the steering wheel at around 61-64 km/h (38-40 mph), a shimmy/shaking can occur.
Cause	Engineering is working on a solution.
Correction	The system is working as intended. The customer should have at least one hand on the wheel at all times.

Version	1
Modified	Released August 20, 2019

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION