



Service Bulletin

Bulletin No.: 19-NA-188

Date: September, 2019

INFORMATION

Subject: Information on Normal Characteristics After Engine is Shut Off

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2020	2020			LM2	
GMC	Sierra 1500						

Involved Region or Country	North America
Condition	Some customers may comment that noises can be heard when the engine has been shut off.
Information	<p>This condition may be caused by components in the engine bay performing a cleaning cycle:</p> <ul style="list-style-type: none"> • Turbocharger Linkage • Exhaust Throttle Valve • Intake Manifold Swirl Valve <p>The noises are normal operating characteristics of the vehicle. It will not impact the designed performance or reliability of the vehicle.</p>

Parts Information

No parts are required for this repair.

Version	1
Modified	Released August 26, 2019

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION