

Subject: Engineering Information – Outer Roof Skin Separating and/or Separated from Roof Frame

This EI has been revised to end the need for information from the field. Please discard PIE0514.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	XLR	2004	2009				

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	August 23, 2019 – Ended the need for further information from the field.