

Subject: Engineering Information – 3 Seconds or Longer Crank Time Before Engine Starts After Vehicle Sitting At Least 20 Minutes

This EI has been revised to end the need for information from the field. Please discard PIE0516.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2018	2019			Equipped with 1.5L, 2.0L (RPOs LYX, LTG)	
GMC	Terrain						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released March 11, 2019 August 07, 2019 – Ended the need for further information from the field.