

Subject: Engineering Information – Engine Oil Life Monitor Counting Down Too Quickly

This PI has been revised to end the need for information from the field. Please discard PIE0518.

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|------------------------|-------------|------|------|----|--|---------------|
| | | from | to | from | to | | |
| Chevrolet | Silverado 2500/3500 | 2019 | 2019 | | | Equipped with 6.6L Engine (RPO L5P) | |
| GMC | Sierra 2500/3500 | | | | | | |

If you encounter a vehicle with the above condition, refer to Bulletin 19-NA-109 for further diagnosis

| | |
|-----------------|---|
| Version | 2 |
| Modified | Released April 09, 2019 Revised August 01, 2019 – Ended the need for further information from the field. |