

Subject: Engineering Information – Left, Right and/or Both Ground Effects Rockers are Loose and/or Pulling Away from Body of Vehicle

This EI has been revised to end the need for information from the field. Please discard PIE0519.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2018	2019				

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released April 01, 2019 August 02, 2019 – Ended the need for further information from the field.