

**Subject: Engineering Information – Water, Moisture and/or Condensation Leak in the Rear Tail Lamps**

*This PI has been revised to end the need for information from the field. Please discard PIE0527.*

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2018	2019			All	All

If you encounter a vehicle with the above condition, refer to Bulletin 01-08-42-001 for further diagnosis.

<b>Version</b>	2
<b>Modified</b>	Released June 17, 2019 Revised August 27, 2019 – Ended the need for further information from the field.