


Latest Vehicle Concern Fixes



Roof Blind Bind / Jam	Range Rover 13 – 19MY Range Rover Sport 14 – 19MY
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• A customer may report that the roof blind does not open smoothly or binds up / jams while operating. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• This may be caused by a roof blind foam strip that has come adrift due to poor adhesion. <p><u>Status:</u></p> <ul style="list-style-type: none">• SSM74501 is being published to address this concern. Should a customer express a concern, please refer to this SSM for repair guidance.	 A close-up photograph showing a grey foam strip attached to a metal track of a roof blind mechanism. The strip appears to be partially detached or misaligned, illustrating the technical issue described in the text.

